

Safety Issue Type: Recalls

June 04 2026 NHTSA Campaign Number: 26V363000

Park Outside: Power Steering Wiring May Catch Fire

A vehicle fire increases the risk of injury.

NHTSA Campaign Number 26V363000

Manufacturer Chrysler (FCA US, LLC)

Components STEERING

Potential Number of Units Affected 1076999

Summary

Chrysler (FCA US, LLC) is recalling certain 2021-2025 Jeep Wrangler and Jeep Gladiator vehicles. The electric hydraulic power steering pump wiring may overheat and cause a vehicle fire, even when the vehicle is parked with the ignition in the "Off" position.

Remedy

Owners are advised to park outside and away from structures, until their vehicle is repaired. Dealers will inspect and replace affected parts, as necessary, free of charge. Owner notification letters are expected to be mailed July 9, 2026. Owners may contact FCA US LLC customer service at 1-800-853-1403. FCA US LLC's number for this recall is 21D. The Vehicle Identification Numbers (VINs) involved in this recall will become searchable on NHTSA.gov on June 11, 2026.

Notes

Affected Products (10)

Vehicle

MAKE	MODEL	YEAR
JEEP	GLADIATOR	2021-2025
JEEP	WRANGLER	2021-2025

Associated Documents (3)

Miscellaneous Document

RMISC-26V363-6990.pdf 0.054KB

<https://static.nhtsa.gov/odi/rcl/2026/RMISC-26V363-6990.pdf>

Recall 573 Report

RCLRPT-26V363-5757.pdf 0.456KB

<https://static.nhtsa.gov/odi/rcl/2026/RCLRPT-26V363-5757.pdf>

RCAK - Recall Acknowledgement

RCAK-26V363-3309.pdf 0.321KB

<https://static.nhtsa.gov/odi/rcl/2026/RCAK-26V363-3309.pdf>